## **MSU Extension Publication Archive**

Archive copy of publication, do not use for current recommendations. Up-to-date information about many topics can be obtained from your local Extension office.

Wood Dust Exposure Levels in Michigan Wood Product Manufacturing Plants Cooperative Extension Service Michigan Energy Conservation Program for Agriculture and Forestry William Droll, Henry A. Huber, Y.G. Feng, Karen Potter-Witter, Department of Forestry July 1991 8 pages

The PDF file was provided courtesy of the Michigan State University Library

### Scroll down to view the publication.



Michigan Energy Conservation Program for Agriculture and Forestry

#### Extension Bulletin E-2316

July 1991

# Wood Dust Exposure Levels in Michigan Wood Product Manufacturing Plants

William Droll Henry A. Huber Y. G. Feng Karen Potter-Witter Department of Forestry Michigan State University

#### Introduction

A study to assess Michigan wood product manufacturers' ability to comply with Occupational Safety and Health Administration (OSHA) workplace exposure limits for wood dust examined 55 wood product manufacturing facilities between October 22, 1989, and October 12, 1990. The study was part of the Michigan Energy Conservation Program's (MECP) wood dust monitoring program, a statewide service provided to forest product producers by MECP in cooperation with the Michigan State University Cooperative Extension Service, the MSU Department of Forestry, and the Michigan Association of Timbermen. This bulletin presents the results of the study and summarizes the principal findings.

#### Health effects of wood dust

OSHA has found evidence that clearly indicates that occupational exposure to high levels of wood dust poses a significant health risk. Therefore, OSHA has set permissible exposure levels for airborne wood dust -5 milligrams per cubic meter (5 mg/m<sup>3</sup>) of air on a time-weighted average over 8 hours. The short-term exposure limit is 10 mg/m<sup>3</sup> of air over 15 minutes for all softwoods and hardwoods except western red cedar. Western red cedar has a lower permissible exposure level -2.5 mg/m<sup>3</sup> for a time-weighted average over 8 hours.

OSHA set the new limits on wood dust not on the basis of any single study; but on the basis of dozens of studies reporting on the respiratory, irritant, allergenic, and carcinogenic properties of wood dust (Occupational Safety and Health Administration, 1989).

The wood dust limit of 5 mg/m<sup>3</sup> set by OSHA has been challenged by woodworking unions as being too high. The unions are petitioning for a standard of 1 mg/m<sup>3</sup> for wood dust. The unions' position is that a 1 mg/m<sup>3</sup> limit would better protect workers' health. This study compared actual exposures to the 1 mg/m<sup>3</sup> limit as well as the current OSHA 5 mg/m<sup>3</sup> limit.

Dust particles irritate the mucous membranes of the nose, throat, and eyes, and even affect the inner regions of the respiratory tract. Cancer of the nasopharynx may develop in woodworkers after several decades of steady contact with fine wood dust (Woods Injurious to Human Health, 1981).

The Inter-Industry Committee on Wood Dust contests the evidence on the carcinogenicity of wood dust and supports the OSHA regulation for limiting the irritant effects of wood dust. The committee recommends the 5 mg/m<sup>3</sup> exposure level as a matter of good housekeeping practice and to promote worker comfort, and it will continue to identify and support needed health research related to wood dust.

#### Methods

This study involved on-site sampling in wood processing facilities throughout Michigan. Through informational mailings and personal invitations, wood product companies were offered the opportunity to have their employees' exposure to wood dust measured at their facility for a nominal charge. The companies were told the data collected would be used by researchers at Michigan State University in compiling group information on wood dust, and that the researchers would not know the identities of the companies.

Michigan Department of Agriculture - Michigan Soil Conservation Districts - USDA Soil Conservation Service Michigan State University's Agricultural Experiment Station and Cooperative Extension Service

MECP is a cooperative effort of the:

Twenty industry segments were surveyed (Table 1). A total of 55 companies were tested; at each company, four or five stations were tested in work areas where wood dust was assumed to be a problem. A total of 267 work station samples were taken.

Table 1. Type of tested for	wood product manufacturers r wood dust exposure.
Number tested	Type of manufacturer
K 6	Furniture
14	Sawmill
4	Pallet
	Sawmill and pallet
2	Veneer
1. 1.	Reel manufacturer
	Planing mill
A AND A	Dimension mill
1 25 1× 2	Molding & picture frames
57 1, 5	Utility pole
5	Cabinet
1410 1 CA ??	Truss manufacturer
2	Window
I the first	Pattern maker
1	Architectural millwork
1 Jan	Log home manufacturer
	Wood souvenirs
1 1 1	Fence
12141	Snowshoe manufacturer
1	_ Cutting board
55 Total	The state of the s

The sizes of plants in the study ranged from small plants employing fewer than 10 workers to several employing more than 100. The majority of the plants tested employed between 15 and 30 workers.

#### **Testing Procedure**

The OSHA-approved procedure for determining wood dust exposure is to conduct gravimetric measurements by using a battery-operated personal air sampler attached to a cassette with a preweighed filter. The cassette is attached to the pump by flexible tubing, which is placed over the employee's shoulder so the air intake of the cassette is within 12 inches of the nose. After the air pump has been calibrated to a constant air flow, the air sampler draws a measured amount of air from the worker's breathing zone through the filter. Wood dust is deposited on the filter during the time it takes to draw that amount of air. Samples to be analyzed for this study were collected with Staplex PST-5 Personal Air Samplers. In each field study, the plant manager and the monitoring technician jointly selected the work stations to be tested. The manager was asked to select the work areas he or she most suspected of having wood dust problems. The technicians conducting the wood dust monitoring were trained in the wood dust monitoring procedures recommended by OSHA.

At each site, the technician calibrated the air samplers before beginning the test. The delicate nature of the sampling equipment and the benefits of the testing were explained to the workers. Workers wore the samplers on belts around their waists, and intake tubes were attached to their shirt collars. The monitoring technician recorded the time each test began and ended. Worker's breaks and extraordinary occurrences were noted. At lunchtime, technicians removed the sampling machines and cassettes, plugging all intake openings. Testing resumed after lunch. The technician also made periodic observations of the workers and inspected the sampling machines during the course of the test.

After the monitoring period, the cassettes were removed from the samplers, sealed, and sent back to Michigan State University for gravimetric analysis.

The weight of wood dust collected on each filter was determined as the difference between the conditioned filter's weight before and its weight after sampling.

#### Results

The results of the study are presented in Tables 2 and 3. Table 2 shows the types of work stations tested, the number of samples taken at each station, the number of samples over 5 mg/m<sup>3</sup>, the number over 1 mg/m<sup>3</sup>, and the percent of the samples in compliance with the OSHA standard. Table 3 shows the range of variation in these measurements. This table shows the minimum, the maximum, and the average time-weighted average for each category of work station and the standard deviation from the mean for each category of work station.

Thirty-seven types of work stations were tested. The work stations were chosen by the plant manager at each site. This resulted in some work stations being tested more than others. For example, the most samples -25 – were taken from cutoff saws, while only one sample was taken from a number of other machines. Statistical inferences drawn from work stations with a small number of samples are less valid than those with a greater number of samples.

The study found a wide range of exposure levels. For example, the average exposure of the 12 head saw areas tested was 1.09 mg/m<sup>3</sup>. The lowest sample showed no measurable wood dust; the highest exposure was 2 mg/m<sup>3</sup>. In contrast, the six maintenance people tested were ex-

Table 2. Dust monitoring results from 55 wood   product manufacturers.					Table 3. Dust monitoring results from 55 wood product manufacturers from 10-22-89 to 10-12-90.						
Work station type	Number of	More than	More than	Percent compliance	Work station type	Ran	Number				
A STATE	sampres	Jing	1 mg	regulations	T CALE	Min	Max	Avg	Std	samples	
Head saw	12	0 -	6	100%	Head saw	0.0	2,0	- 1.1	0.6	12	
Edgesaw	16	2	- 11	88%	Edgesaw	0.5	56.4*	6.3	13.3	16	
Chipper	4	0	3	100%	Chipper	0.7	2.4	1.7	0.7	4	
Trimsaw .	17	4	-11	76%	Trimsaw	0.3	58.3*	6.5	13.4	17	
Grader	7	0	6	100%	Grader	0.6	3.9	2.0	1.2	7	
Debarker	16	1	10	94%	Debarker	0.2	8.0	1.9	2.0	16	
Tailer	2	0	11	100%	Tailer	0.5	2.4	1.4	1.0	5 2, je	
Resaw	5.	2	4	60%	Resaw	0.5	13.1	4.7	4.5	5	
Molder	2 9	2	6_	78%	Molder	0.3	10.7	3.0	3.1	9	
Planer	8 -	0	4	100%	Planer	0.5	1.9	1.1	0.5	.8	
Bolt gangsaw		1.1	6	89%	Bolt gangsaw	0.2	6.2	2.2	2.0	5.9	
Cutoff saw	25	~3 <	20	88%	Cutoff saw	0.3	52.7*	4.7	10.9	25	
Shaper	3	2	2	33%	Shaper	0.5	6.5	4.4	2.7	3	
Router	8	4-	8	50%	Router	2.4	8.1	4.8	1.9	8	
Panel saw	3 -	0	2	100%	Panel saw	0.4	3.4	1.7	1.3	3	
Gang rip	7	-(	4.	86%	Gang rip	0.9	8.1	2.4	2.4	7	
Nailer	- 4	1-20	4	75%	Nailer	2.3	5.4	3.9	9 1.3	4	
Sander	21	6	T 13 C	71%	Sander	0.5	028.9*	4.8	7.6	21	
Ripsaw	19	-2	13	89%	Ripsaw	0,2	45.3*	4.4	9.9	19	
Drilling	4	0 (-	2	100%	Drilling	0.5	2.2	1.3	0.7	4	
Maintenance	6 6	5	5	17%	Maintenance	0.8	88.0*	19.7	30.7	6	
Dry kiln	1	0		100%	Dry kiln	1.0	1.0	1.0	na	1	
Bandsaw	1.6	2	5	67%	Bandsaw	0.9	74.5*	22.0	30.1	6	
Material handling	9		4	89%	Material handling	0.3	7.8	2.1	2.3	9	
Bagger	4	3	4	25%	Bagger	4.9	8.0	6.5	na	54	
Misc. wood tools	21	0	10	100%	Misc. wood tools	0.2	4.2	1.3	0.9	21	
Foreman	2	0	1	100%	Foreman	0.8	2.0	1.4	0.6	2	
Dowel finisher	1	0	1	100%	Dowel finisher	1.2	1.2	1.2	na	1	
Notcher	3.72	0	2	100%	Notcher	0.5	2.1	1.5	0.7	3	
Veneer jointer	2	CA:	1	50%	Veneer jointer	0.5	6.5	3.5	3.0	2	
Veneer sander		0	0	100%	Veneer sander	0.6	0.6	0.6	na	1	
Veneer splicer	- 3	I O	1	100%	Veneer splicer	0.3	2.1	1.0	0.8	3	
Veneer welder	N 1	0	ri-	100%	Veneer welder	(1.7	1.7	1.7	na	- 1	
Veneer drier		0		100%	Veneer drier	3.7	3.7	3.7	na	Î.	
Veneer clipper		0	De 1	100%	Veneer clipper	1.3	1.3	1.3	na.	Te test	
Mult carver	The second	ò	1 0	100%	Mult. carver	0.5	0.5	0.5	na	11	
Pattern maker	5	.);-j	5	80%	Pattern maker	1.2	5.4	2.5	1.5	5 . 5 A	
	007	1 21	170	0404	* Note: Some high exp	osure level	s occurred be	cause of one	-time expos	ure under unusua	

posed to dust concentrations averaging 19.55 mg/m<sup>3</sup>. The highest reading for the maintenance personnel was 87.98 mg/m<sup>3</sup>; the lowest was 0.75 mg/m<sup>3</sup>.

Forty-four (16 percent) of the 267 samples exceeded the 5 mg/m<sup>3</sup> limit established by OSHA; 178 (64 percent) of the 267 samples exceeded 1 mg/m<sup>3</sup>.

Twenty-two of the 55 plants (40 percent) sampled had at least one sample indicating wood dust concentration above 5 mg/m<sup>3</sup>. Fifty companies (90 percent) had at least one sample indicating wood dust concentration above 1 mg/m<sup>3</sup>. Only five (9 percent) of the companies tested had no tests indicating dust levels above 1 mg/m<sup>3</sup>. Of these five companies, three were sawmills tested in the summer while it was raining. (The effect of weather on test results will be discussed below.)

The on-site sampling occurred from October 22, 1989, through October 12, 1990. The testing procedures remained consistent throughout this time, but the results differed with the time of year the testing occurred (Tables 4-7). No testing was done from April 20 through June 27, 1990.

Summary of wood dust exposure data by company.



Figure 1. The percentage of the 55 companies tested having at least one station exceeding 1 mg/m<sup>3</sup> or 5 mg/m<sup>3</sup>.

Seventy-seven percent (104 out of 136) of the work stations tested during the winter were under the 5 mg/m<sup>3</sup> limit (Table 4). During the summer, 90 percent (118 of the 131 of the work stations tested )were under the 5 mg/m<sup>3</sup> limit (Tables 6 and 7). In almost every case, the samples taken in the summer were lower than their winter counterparts.

During the winter testing, 70 percent (19 out of 27) of the companies had at least one work area with levels over  $5 \text{ mg/m}^3$  (Figure 2). All of the companies tested at this time had at least one station over 1 mg/m<sup>3</sup>.

## Summary of wood dust exposure data by season.



Figure 2. The percentage of the 28 companies tested during the summer and the 27 companies tested during the winter with at least one work station that exceeded 1 mg/m<sup>3</sup> or 5 mg/m<sup>3</sup>.

During the summer, 28 percent (8 out of 28) of the companies had at least one station over 5 mg/m<sup>3</sup>. Eighty-two percent (23 out of 28) had at least one station over 1 mg/m<sup>3</sup>. During the summer, 17.8 percent (5 out of 28) had all stations in their facilities test under 1 mg/m<sup>3</sup>.

In general, three factors contributed to reduced exposure rates during the summer: the opening of doors and windows, higher humidity, and the use of individual fans for cooling.

On rainy days, work stations usually had dust levels much lower than expected, based on other tests of similar machines on dry days. The workers indicated that they believed that the higher the humidity, the lower the apparent dust levels. No precise data on humidity were collected during this study, but the technicians did observe lower wood dust levels during days of apparent high humidity or rain.

#### Variation in wood dust exposure

A number of variables could be responsible for the wide variation in wood dust exposure rates of similar work stations. The total amount of wood dust found at a specific work station is the result of a combination of many components, including the dust collection system used, worker experience, work methods, weather, the species of wood being processed, tool maintenance, and the type of Table 4. Wood dust exposure sampling results from 27 Michigan wood product manufacturers from 10-22-89 to 4-19-90 (winter testing).

Table 5. Wood dust exposure from 27 wood product manufacturers from 10-22-89 to 4-19-90 (winter testing).

Work station type	F. NUM	per or sa	mpies	osha	(winter testing).					1-1-1
	Total	More than 5 mg	More than 1 mg		Work station type	Range of variation: airborne wood dust, mg/m <sup>3</sup> of air				Number
				regulations	- 1.5 m.1 .	Min	Max	Avg	STD	sauprea
Head saw	10	0_1	6	100%	Head saw	0.0	2.0	1,1	0.7	10
Edgesaw	tt-	2	8	82%	Edgesaw	0.6	56.4	8.1	15.7	11-
Chipper	121	0	T. 1 - 7	100%	Chipper	0.7	2.2 ,	1.5	0.7	. 2
Trimsaw 5	10	3 -	7 6	70%	Trimsaw	0.3	58.3	9.6	16.7	10
Grader	6	0	- 5	/ 100%	Grader	0.6	3.9	2.0	1.3	6
Debarker	7	_ 0 、	5 )	- 100%	Debarker	0.3	3.7	- 1.5	1.0	7
<b>Failer</b>	31.	0		100%	Tailer	2.4	2.4	2.4	0.0	. 1
Resaw	4	2	4	50%	Resaw	2.2	13.1	5.8	4.4	4
Molder	3.0	2	3	33%	Molder	1.6	10.7	6.1	3.7	- 3 =
Planer	6	. 0	4	100%	Planer	0.5	1.9	1.2	0.5	6
Bolt gangsaw	. 5	11-	5	80%	Bolt gangsaw	_1.1	6.2	3.4	1.9	5 5
Cutoff saw	11 -	3	9	73%	Cutoff saw	0.3	52.7	-8.4	15.6	- 11 ·
Shaper			220		Shaper					1-1-5
Router	4	2	4	50%	Router	2.6	8.1	5.3	2.1	4
Panel saw	2-1-5	0	1	100%	Panel saw	3.4	3.4	3.4		12
Gang rip	5	1	4	80%	Gang rip	0.9	8.1	3.0	2.6	5
Nailer	1. 14		4	75%	Nailer	2.3	5.4	3.9	1.3	4
Sander	2 TE 7. 2	4	6	43%	Sander		28.9	9.9	11.1	57
Ripsaw	6	1.0.	~ 42	100%	Ripsaw	0.7	3.6	1.8	1.0	6
Drilling	1.1	0 -	0	100%	Drilling	0.5	0.5	0.5	0.0	15
Maintenance	1 5	4	4	20%	Maintenance	0.8	8.8	6.0	2.8	5
Dry kiln	1		, 0	100%	Dry kiln	1.0	1.0	1.0	No F	1
Bandsaw	3	1-2-19/10-	3-	67%	Bandsaw	, 1.0 -	52.7	18.3	24.3	1 3
Material handling	4	1-	2	75%	Material handling	0.3	7.8	2.6	3.1	4
Bagger	4	- 3	4	25%	Bagger	4.9	8.0	6.5	1.4	44
Misc. wood tools	5.17	Po-	AF.	100%	Misc. wood tools	2.9	2.9	2.9	5124	S. 1 .
Foreman	27	0	SI.	100%	Foreman	0.8	2.0	1.4	0.6	2
Dowel finisher	2.1	0	1	100%	Dowel finisher	1.2	1.2	1.2	0.0	51
Notcher	n-2)	0 1	2	100%	Notcher	1.8	2.1-	2.0	- 0.1	2
Veneerjointer	2	51	1.1	50%	Veneer jointer	0.5	6.5	3.5	3.0	2
Veneer sander	11		0	100%	Veneer sander	0.6	0.6	0.6	0.0	, 9 1
Veneer splicer	2 3	205	1	100%	Veneer splicer	0.3	2.1	1.0	0.8	3
Veneer welder	F	. O'	1	100%	Veneer welder	1.7	1.7	1.7	5	277
Veneer drier	1		- 1	100%	Veneer drier	3.7	3.7	3.7	Re ista	1.5
Veneer clipper	14	-0	1	100%	Veneer clipper	1.3	1.3	1.3	0.0	1
Mult. carver		「「「」	A. L.	1. F. J	Mult. carver	-11-				7
Pattern maker			The set		Pattern maker		14	in the	Der 19	it is the
Total	136	31	104	77%	* Note: Some high expo	osure levels	occurred ber	ause of one	time exposur	e under unusu

Table 6. Wood dust exposure sampling resultsfrom 28 Michigan wood product manufacturersfrom 6-28-90 to 10-12-90 (summer testing).

Table 7. Wood dust exposure from 28 Michigan wood product manufacturers from 6-28-90 to 10-12-90 (summer testing)

The second and	Number of samples			Percent	10-12-90 (summer testing).					and the state
Work station type	Total	More	More than 1 mg	compliance with current OSHA regulations	Work station type	Rang	Number			
	Y	Jing			14 34	Min	Max	Avg	STD	samples
Head saw	2	0	12 O M	100%	Head saw	0.7	0.9	0.8	0.1	2
Edgesaw	5	0	3 3	100%	Edgesaw	0.5	4.1	2.2	1.3	5
Chipper	2	0	2	100%	Chipper	1.3	2.4	1.8	0.5	2
Trimsaw	7		4	86%	Trimsaw	0.5	5.3	2.0	1.6	, <b>7</b>
Grader	1.1	0	2 1-	100%	Grader	1.7	1.7	1.7	0.0	1 1 1
Debarker	9	1	- 5	89%	Debarker	0.2	8.0	2.15	2.4	9
Tailer	12	0	0	100%	Tailer	0.4	0.4	0.4	P.P.Y	1
Resaw	1	0	0	100%	Resaw	0.4	0.4	0.4	0.0	1.1-
Molder	6	0	3	100%	Molder	0.2	2.9	1.5	1.0	6
Planer	2	0 .	2,00	100%	Planer	0.4 ?	0.8	0.6		2
Bolt gangsaw	4	0	1,	100%	Bolt gangsaw	0.2	1.2	0.7	0.3	». A .
Cutoff saw	14	0	11	100%	Cutoff saw	0.2	-4.7	1.7	1.0	14
Shaper	3	2	2	33%	Shaper	0.5	6.5	4.3	2.7	3
Router	4	2	- 4	50%	Router	2.3	6.2	4.3	1.5	4
Panel saw	2	0	1	100%	Panel saw	0.3	1.4	0.9	0.5	2
Gang rip	2	0	0	100%	Gang rip	0.9	0.9	0.9	0.0	2
Nailer	X		200	CHER AND	Nailer	155		T.	and the second	1. Y. 200-
Sander	1.14	2	7	86%	Sander	0.4	9.3	2.3	2.5	n 14
Ripsaw	13	1 2	9	85%	Ripsaw	0.2	45.2	5.5	11.8	13
Drilling	3 1	0	2	100%	Drilling	0.7	2.2	1.6	0.6	3
Maintenance	11	1	2.1.	0%	Maintenance	87.9	87.9	87.9		
Dry kiln			SE CERT	the KA	Dry kiln		24			- Starter
Bandsaw	3	1	2 ~	67%	Bandsaw	0.8	74.4	25.5	34.5	5 3
Material handling	5	0	2	100%	Material handling	0.2	3.3	1.6	1.3	5
Bagger	172X	i al	S Stat		Bagger		Carlot K			4
Misc. wood tools	20	0	9	100%	Misc. wood tools	0.2	4.1	1.2	4 0.8	20 -
Foreman	Le La St			the state	Foreman			Tak		
Dowel finisher	1	A. Y.		K-L	Dowel finisher	1. 1. 4			5	1.29.1
Notcher	- 1	0	0,	100%	Notcher	0.4	0.4	- 0.4	the trans	1
Veneer jointer	al a c		~ ~	JOC 1	Veneer jointer	)		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		1.14
Veneer sander		-x < ->	13.03	P	Veneer sander	1.51			× 4	A H Y
Veneer splicer					Veneer splicer		Norman Terrar		n t et	
Veneer welder		-x Que		7	Veneer welder	1 de		× +-	in ,	N. S.
100% Veneer drier		1 the get			Veneer drier	( The second sec	16.50	S. P. S.		4
Veneer clipper		Ji T	Star	SAL Y	Veneer clipper	1 1	17.25	MAR		
Mult. carver	1	TO	- O	100%	Mult. carver	0.4	0.4	0.4	0.0	Ript
Pattern maker	5	1	5	80%	Pattern maker	1.2	5.4	2.4	1.5	5
Totals	131	13	74	90%	All and I	NES!	Stat 24	274	F. S. S.	State of the state

manufacturing that takes place at and around that work station. Though no two manufacturing facilities or no two work stations were identical in all respects, factors that may have contributed to the variations in exposure rates for similar work areas were observed by the technicians doing the on-site sampling. These on-site observations are the basis for the following comments.

Systematic study of a wood products manufacturer's dust control system could suggest means of improvement. Improving the hood design, attaching ducts at 60 degrees or less and closing the shutoffs on unused machinery have been reported to reduce wood dust exposure (OSHA's Wood Dust Regulation, William McCredie). Several dust collection systems observed by the technicians during this study could have been improved by using these methods.

Initial purchases of dust collection systems are often made without giving sufficient thought to the design or the future needs of the companies (Furniture Design and Manufacturing, July 1989). This appeared to be the case in some of the manufacturing sites in this study.

Modifying a company's dust collection system after installation can make the system inadequate. Whenever an air line is added or taken out of service, the entire system is affected. Adding a line to an existing system increases resistance and reduces the system's total effectiveness.

Modifications of ductwork were noticed during the on-site sampling. Some of the modifications were held together with duct tape, which is not recommended as a primary method of joining because the fabric deteriorates and has no elasticity. Leakage wastes energy and costs money. A 10 percent leakage in a 50,000 cfm system will lose a volume of air equal to the amount needed to provide air exhaust for five or six machines (Air Handling Systems, Manufacturer's Service, 1990).

Another problem associated with tapping into existing ductwork is that joining one line to another at the wrong angle creates a dead air space where dust accumulates. This reduces the effective diameter of the pipe and creates a potential fire hazard.

Hood design at the woodworking tool is also important in improving wood dust control. If dust cannot enter a hood, the system will not pick it up. It will then accumulate in the air around the worker.

Dust collection is the final answer to any dust exposure problem. Consideration should be given to reducing the amount of work the system must do by reducing the amount of dust generated. Proper tool geometry can affect the type and amount of wood dust generated. As the rake angle and depth of cut increase, the sizes of the particles increase, there is better chip formation, and the surface quality of the work piece is improved. As the wood particles get larger, they are more easily controlled, and tool wear is reduced. Adjusting machining conditions such as depth of cut, feed rate, tool speed, and tool geometry can help reduce tool wear and wood dust problems (FDM, June 1989).

Reducing static electricity can also make the collection of wood dust easier. Static electricity sometimes causes wood dust to accumulate on machinery, work pieces, and even the workers.

Electrostatic charges occur whenever two materials come in contact and then separate. For example, when a sanding belt on a sanding machine separates from the idlers and from the piece being sanded, the dust particles that arise have the same static charge, so they are repelled from one another. They are attracted and adhere to anything that has the opposite charge--that could be the worker, the work piece, or the machine. This makes the collection of this dust very difficult.

Static charges can be reduced in a processing plant by increasing the humidity of the air during the winter heating season.

Work practice controls include housekeeping practices, materials handling, and personal hygiene. In many cases, judicious application of such practices can reduce employee wood dust exposure (Wood and Wood Products, July 1989).

Observations made during this study concur with those in a previous study done by Clayton Environmental Consultants, Inc., on the primary work practice that contributes significantly to employee exposure to wood dust: using compressed air to clean dust off equipment and workplace areas. This study and the Clayton study suggest that using compressed air for cleaning is a major source of exposure to the person doing the cleaning and to the employees in adjacent areas.

Alternatives to using compressed air include sweeping or vacuum cleaning. For controlling wood dust, vacuuming is preferred. Available information suggests that it may not be practical to replace compressed air with these methods in all applications because of the efficiency and effectiveness of the compressed air (Wood and Wood Products, July 1989).

#### Conclusions

The results and observations of this study indicate that most, if not all, machines and processes tested could achieve exposure levels below 5 mg/m<sup>3</sup> if reasonable local exhaust ventilation were used and the exhaust system was properly designed and maintained.

Sixty-six percent (178 out of 267) of the work stations tested had dust levels above 1 mg/m<sup>3</sup>. This suggests it would take considerable effort and expense to comply with the wood dust limits suggested by the woodworking unions.

Only two of the 55 companies tested were able to achieve exposure levels below 1 mg/m<sup>3</sup> at all the work stations tested. It appears, from the observations of the technicians, that these companies would do so regardless of the time of year or the weather. Both of these companies emphasized maintenance on all levels and had more than sufficient dust collection systems. These two plants were moderately aged, established companies that had initially well designed dust collection systems.

Managers of the companies with the higher exposure readings should focus energy and resources to reduce wood dust levels at their facilities. To obtain optimum benefit from the efforts toward this end, managers need to find expert help before making any equipment expenditures.

#### Implications of the Study

This study identified many factors – weather, dust collection systems, and machine setups – that seemed to influence the wood dust exposure levels in the companies tested. Large variations in exposure rates in similar work stations could not be explained entirely by the factors considered in this study. The following factors need further study: air flow rates of the dust collection systems, effect of tool setup, feed rate, horsepower, revolutions per minute of cutter heads, and geometry of cutter heads. The influence of weather needs further study: for example, a direct comparison of dust levels during winter and summer and a study of the effect of humidity on exposure levels.

Further studies in these areas could help reduce workplace wood dust exposure levels and help make work areas safer and more comfortable.

#### Bibliography

Hausen, Bjorn. 1981. Wood Injurious to Human Health. New York: DeGruyter.

Bhattacharyya, Gouri, and Richard Johnson. 1977. Statistical Concepts and Methods. John Wiley and Sons, Inc.

McCredie, William. 1990. OSHA's Wood Dust Regulation.

Anon. 1989. Meeting the Wood Dust Challenge. Furniture Design and Manufacturing, June, pp. 60-67.

Manufacturers Service Company. 1990. Air Handling Systems, p. 34.

Anon. 1989. Modern Woodworking Machinery and Dust Control. Wood and Wood Products, July, p. 102-106.

Occupational Safety and Health Administration. 1989. Air contaminants: final rule. Federal Register 54(12): 2329-2984.

Clayton Environmental Consultants. 1988. Final report on an industry-wide study of wood dust exposures for the Inter-Industry Wood Dust Coordinating Committee. OSHA docket No. h-020, October 4, 1988.

Printed on Recycled paper with vegetable-based inks. New 8/91-2M-KMF-MP, Price 60¢, for sale only. FILE 24.7 (Forest Products)

MSU is an Affirmative Action/Equal Opportunity Institution. Cooperative Extension Service programs are open to all without regard to race, color, national origin, sex or handicap.

"This bulletin was prepared with the support of the U.S. Department of Energy, Grant No. DEFG0276CS60204. However, any opinions, findings, conclusions, or recommendations expressed herein are those of the author(s) and do not necessarily reflect the views of DOE."

Issued in furtherance of Cooperative Extension work in agriculture and home economics, acts of May 8, and June 30, 1914, in cooperation with the U.S. Department of Agriculture. Gail L. Imig, Director, Cooperative Extension Service, Michigan State University, E. Lansing, MI 48824.

This information is for educational purposes only. Reference to commercial products or to trade names does not imply endorsement by the Cooperative Extension Service or bias against those not mentioned. This bulletin becomes public property upon publication and may, with credit to MSU, be reprinted verbatim as a separate or within another publication. Reprinting cannot be used to endorse or advertise a commercial product or company.