

- (21) Improper use of flexible electric cord.
  - a. Cord running through a wall.
  - b. Use of flexible cord in place of permanent wiring.
- (22) Failure to use approved storage for gasoline.
- (23) Welding cables in poor condition; improperly spliced.
- (24) Failed to have grounded 55 gallon drum of Class I flammable liquid. Any Class I liquid (gasoline or solvent) must be grounded to container that is being filled to eliminate chance of fire from static spark.
- (25) Failed to provide emergency eye wash in battery charging areas and areas where acid is used.
- (26) Failed to have two ways of egress from a boiler room.
- (27) Failed to secure compressed gas cylinders. (Must be chained to a wall in an upright position.)
- (28) Failed to maintain free access to electrical control panels.
- (29 & 30) Failed to provide guard over floor openings.
- (31) Failed to provide approved respirator in the chlorine room at swimming pool.
- (32) Failed to provide exit signs.
- (33 & 34) Failed to provide guards on fly wheel of circulator pump and fans with openings no more than 1/2 inch.
- (35) Access to exits blocked in storage building.
- (36) Failed to provide cover to ladder of lift station which is safe and secure.
- (37) Failed to provide landing platforms or safety device on ladders of twenty feet or more at lift stations and water towers.
- (38) Failed to provide guard on pump shaft.
- (39) Failed to prohibit smoking or open flame in gun powder storage area.
- (40) Unsafe overhead storage in storage building.
- (41) Failed to maintain inspection records on crane (heavy equipment).
- (42) Failed to provide fire extinguisher in cab of crane.
- (43) Failed to provide boom stops on crane ANSI B30.5-1968 Sec 5-1.9.1a
- (44) Failed to provide barrier guards around hoists and dumb waiters.
- (45) Failed to guard live contacts on terminals on transformers operating at over 50 volts in an area in which employees are exposed.

**Serious Violation:**

(1) Employer failed to furnish employees conditions and a place of employment free from recognized hazards that were likely to cause death or serious injury to employees by allowing the unsafe conditions to exist at the Hostatler building which is in such a rundown condition that employees have fallen through parts of the building.

Questions can be answered by contacting Mr. Ivan Russell or Mr. Al Hartman at the Department of Labor and Industry, 296-2116.

**SPECIAL NOTICE:** As of October 1, 1975 the Minnesota Golf Course Superintendents' Association will once again headquarter in the offices of the Minnesota Golf Association. The address is 7100 France Avenue South, Suite 207, Edina, Minn. 55435. Telephone 612/927-4643. The offices are open year around, five days a week from 8:30 a.m. to 5:00 p.m.

All items for the HOLE NOTES as well as any other business should be sent or called in directly to the offices.

**CUSHMAN<sup>®</sup>**

<p>Golf Cars</p>  <p>Gas or Electric</p>	<p>Turf Care System</p>  <p>3 &amp; 4 wheel turf trucksters</p>
--	--

**SALES • SERVICE • PARTS**

**CUSHMAN MOTOR CO., INC.**  
 2909 E. Franklin Avenue • Minneapolis, Mn. 55406  
 PHONE: 612 • 333-3487