

in winter on compact, attractive and economical basis.

Checkrooms often are poorly located and arranged.

Locker-rooms usually are too dark. Skylights might be an answer for some darker locker-rooms.

Locker-room ventilation must be good.

Although locker-rooms are where liveliest "life" of the club is in evidence, painting of lockers and walls, ceilings and floors usually is anything but cheery. Locker-room rugs, carpeting and furniture are chosen with dirt and wear factors so strongly in mind, they're generally ugly.

Shower-room ventilation and light often are bad. Cheap plumbing in showers and washrooms is chronic expense for club and tends to give the whole club and its membership a "cheap" atmosphere.

Locker-rooms and bath departments seldom laid out with an idea of facilitating complete and quick cleaning by small staff.

Locker-room service bar proper location can do a lot in improving service and reducing operating costs.

Kitchen, dining, and grill room layout at golf clubs due for drastic revision due to recent legislation concerning employees.

Considerable study is needed to devise new methods of retaining country club distinction of service without great increase in expense, under recent laws.

More thought needed in location and arrangement of employees' quarters, even if such quarters are merely a room for a caretaker.

New problems have come with growing popularity of swimming pools, and necessity of extending outdoor service.

Few clubhouses make most attractive use of possibilities of food service, and dances on verandas. Most verandas are simply porches nailed onto the clubhouses.

Possibilities of men's lounge and bar areas on upper decks of clubhouse porches rarely have been utilized.

Pro-shop needs to be fitted into architectural plan for convenience for both men and women members and handiness to first tee and eighteenth green.

Storage space for emergency furniture, and small repair shop too seldom seen in clubhouses.

Clothes drying facilities generally are inadequate.

Emergency location of club bars right after repeal often was so far in error

the club bar-rooms now have the stale beer smell of a cheap saloon.

Failure to provide for rapid growth in women's demand for lockers and showers is one of the chief headaches of golf clubs now.

Many clubhouse sewage disposal systems unable to care for amount of sanitary napkins received.

Parking space and walks from it usually are afterthoughts in clubhouse planning.

Manager's office often is located at worst possible place for him to be "every place at once," where members expect the manager to be.

Food and beverage storage facilities many times not in location where delivery and service is convenient; checking is facilitated, and perishable foods can be kept in best possible condition if storage location is correct.

With winter sports programs growing, more attention has to be paid to use of fireplace for emergency heating.

Decided trend toward menu simplification (most apparent at the ritziest clubs) must be studied for possible effect on kitchen design.

Small, smart and good; rather than large, showy and cheap, seems to be the lesson that has been impressed on golf clubs during the two decades that saw the greatest amount of golf clubhouse use.

**S. Cal. Greensmen Plan Turf Show—**  
A turf equipment show coupled with an educational program, sponsored by the Southern California Greenkeepers' Assn., will be held May 22-23 at Griffith Park GC, Los Angeles. This will be the first show of its kind put on in the Pacific Coast section, and every effort is being made to insure its success. The Los Angeles Chamber of Commerce has pledged its cooperation, and has extended invitations to all in the Western area who are interested in the maintenance and growing of fine turf, to attend.

The equipment show will be held at Griffith Park beginning at 9. a.m. and lasting until 12:30 p.m., both days. The educational program will be held in the afternoon, on the two days, at the Embassy hotel in Los Angeles, where expert speakers will deal with knotty turf problems. The Embassy hotel has been selected as convention headquarters; reasonable accommodations are still available there for the convention, officials have announced.