GEOFFREY S. CORNISH

Golf Course Architect

Fiddler's Green Amherst, Mass.
Phone: 413-253-3913

For more information circle number 140 on card



ROBERT BRUCE HARRIS

Golf Course Architect

MEMBER AMERICAN SOCIETY OF GOLF COURSE ARCHITECTS

645 N.MICHIGAN AVENUE WHItehall 4-6530 CHICAGO 11 - 1LL.

For more information circle number 170 on card

Art Wall Jr. GOLF COURSE ARCHITECTS

Master Planning • Site Analysis Plans Specifications • Supervision Irrigation Systems • Storage Ponds

Bellante and Clauss Bldg. Scranton, Pa. 717-344-8531 Suburban Station Bldg. Philadelphia, Pa. 215-564-2444

For more information circle number 134 on card

GOLF TEES

21/8" white or assorted colors, \$4.10 per M-20 M or more, 1966 catalog on request.

Al Northup Mfg's Rep.
P.O. Box 189, 262 Colonial Ave.
Williston Park, L I., N. Y.

For more information circle number 166 on card

Best Idea

Draining Those low areas

By EUGENE P. YAVARSKI

In early Spring, we seem to be the last course to open, due to casual water still standing. I have not yet been able to tile these low places, so I devised this drainage tool to get the water off as soon as possible. Basically, it consists of a sub-soiler. However, I added a chain and a 2½ inch pipe. I coned the nose and then fastened the chain to it. As the sub-soiler is pulled through the ground, the pipe forms a three inch drainage hole 15 inches under the sod. I was disappointed the first try, because the sub-soiler tore up too much sod and made a very unpleasant job. So I mounted



a plow-coulter in front of the arm of the sub-soiler. I can now drain areas with no damage to the turf. The only tell-tale marks are a ½ inch slice through the ground, and a slight heave of the ground of about 1½ inches. This heave will fall to normal after the Spring thaw.

GOLFDOM is looking for new ideas for doing key jobs easier and better around the golf club. We'll pay \$20 for each one published. 150 words or less. Send to GOLFDOM, 800 Second Avenue, New York, N. Y. 10017.