

Every Golf Course needs THIS!

Introducing, the world's **MOST ADVANCED** Environmental Center available.







1.800.816.4041 Phone: 815.462.1300 Fax: 815.462.4036

21719 S. Center Avenue. Unit D,New Lenox, IL 60451



GREEN CREASE



Got Ball Marks?



ialt.

- Provides Heat and Drought Tolerance
- Rich in Amino Acid Content
- University Tested and Proven

- GreenNcrease increases shoot density by 30-40% on bentgrass greens.
- Ball marks recover faster. Greens recover quicker from mechanical damage.
 - Mechanical stress is greatly reduced with healthier cleanup laps on greens.



See us at the 2014 GIS Show in Orlando, Booth 2807, Feb. 5-6

Ajinomoto Specialty Fertilizers Ajinomoto North America, Inc. 1 Ajinomoto Drive | Eddyville, Iowa 52553 | 563-260-1838



Westmoreland

les of Tile at

Luke Cella, MAGCS

PHOTOS: LUKE CELLA AND TODD FYFFE

Todd Fyffe woke up in the middle of the night to a flashing red sliver of light coming through his bedroom window. When he went to bed the previous evening it had started to rain. The Westmoreland Superintendent's home sits on the south border of the golf course property. When he woke to the strobe, it was still raining.

Six inches of rain had fallen on the partially installed system. It was tested beyond measure with this storm. The flashing light was coming from a power substation relay that controls the main pump on the drainage system. As Todd looked past the strobe, he could see its reflection on a body of water covering the 8th, 9th, and 18th fairways. The new system had failed.....until a relay was reset and the water was pumped off the property as designed.

Westmoreland Country Club is bordered by three different communities: Wilmette to the north, Skokie to the west and Evanston to the east. The country club was founded in 1911 when "a group of men from Evanston Golf Club, locat-



Over 11 miles of the waffle drain pipe was installed throughout Westmoreland Country Club. The two pieces of plastic are wrapped by a geotextile fabric.

ed on the canal banks of Evanston, became dissatisfied with the space limitations of their course as the City of Evanston expanded." Hence the name – a group that moved west for more land. The original design of the course was done by William Watson in 1912. This design underwent a significant change in 1920/21 when William Langford and A.W. Tillinghast completed a redesign of the course. Arthur Hills influenced a renovation in the early 1990s but the club still holds true to Watson's original routing.

Oddly enough, one of the original reasons the founder's of Westmoreland Country Club chose the 128-acre site was "because it was under laid by a 25-foot bed of gravel, which provides ideal drainage for turf." Somehow, somewhere, something went wrong. The course does not drain at all. Its' soils are a high-organic based muck that hold water and impede root penetration and growth. An inch of rainfall can limit cart traffic for days as the course tries to cast off gravitational water. The physical evaluation from ISTRC show the soil is comprised of 70% sand but the high organic content holds water. Overall there is a 13:1 ratio of water to air with a 70% water holding capacity. All this equals a dreadfully slow infiltration rate of .01 inches per hour.

Drainage has to be the toughest sell to any membership; it is something that no one ever sees. At least with an irrigation system, members will occasionally see a head on, or at the very least, the pump house. If you think about it even further, a drainage system is air, albeit underground. Todd explained to me, the members of the club have been

very supportive of this project, they really understand the importance of being able to take water away. After so many years of repairing and replacing turf due to flooding, the members and Todd are ready for it.

When most of us think of turf injured or killed by floods, we attribute it to some body of water, a creek, river or stream over flowing its bounds and not receding for a long period of time. Westmoreland has no water feature that flows through the property, only an 18" buried storm drain line that was installed in the1960s. Throughout the years, every drain line on the property has been hooked into this concrete pipe. The pipe runs from the east to the west and before it enters into the Village of Skokie's storm / sanitary sewer it is further reduced by a 12" restrictor fitting. When large storms came



Todd Fvffe, Golf Course Superintendent at Westmoreland Country Club told me about a drainage project that the club embarked upon.

through, it was not uncommon for portions of the course to be covered in water for two or three days. That 18" mainline could only take so much water and as Todd explained, "the soils here have become muck and clogged, creating temporary ponds in many spots throughout the property when it rains heavily."

One of the regulations through the permitting process by the Municipal Water Reclamation District (MWRD) of Greater Chicago, states that they are only able to accept surface water in their system, not ground water. So any seepage water that flows from the surface through the soil

profile (most drainage systems on any golf course) cannot be sent downstream through piping, only on the surface. In addition, because of the golf course's tremendous water holding capacity, the design had to release water slowly into the Village of Skokie's storm / sanitary sewer. Working within these confines, Westmoreland hired Dennis Hurley at Turf Drainage Company of America to design the system, Gewalt-Hamilton (a local engineering firm) to represent the club and manage the project, and Leibold Irrigation to install the system. On paper, the solution was to increase the golf course ponds water holding capacity, pump seepage water to the ponds (make it surface water) and then release it slowly when needed into the MWRD system.

The new design called for an increase in the water holding capacity of the ponds on the course. Prior to the revamp, the ponds on the course had a potential holding capacity from the normal water level to high water level of 1,124,500 gallons of water. Upon completion the pond capacity was increased to 7,600,000 gallons at normal water level by raising two pond banks on property. If heavy rains are expected, by lowering the ponds by 4 feet, the ponds on the course have the capacity to hold over 12,300,000 gallons of water; this is the equivalent of a 4 inch rainfall across the 120 acre property with zero soil absorption or seepage.



wrapped in fabric allow air and water exchange from the surrounding soil too.

Water runs through the main drain line from east to west. The main ponds on the golf course are on the eastern and middle section of the property. Water had to be captured and pumped against the natural pitch and flow of the property. The system works by capturing surface water across the course through a series of drains

As with most drainage systems, this drainage system begins using the topography of the course to move water by gravity. In several fairway locations Todd showed me small catch basins where the drains actually come to the surface. Using a geotextile fabric wrapped around a wire structure, these small basins are able to capture water not only from the playing surface, but also from the soil profile as water can seep in through the fabric. Over 150 of these smaller basins



One of the Irrigation Drive Pumps (IDPs) in the early stages of installation in a sump. They sound more complicated than they really are.

have been installed as part of the project. Some of the basins are cylindrical while others are rectangular depending upon the need of the specific site. The other key component that is terminated into these basins, and larger sump pits, is the actual subsurface drainage. The piping system that was installed utilized a waffle drain, a system that has a core of two pieces of plastic wrapped by a geotextile fabric. This type of piping provides a greater collection area for water to enter the flow area than conventional round perforated pipe.

Continued on page 22

Larger structures installed include sump pits (both concrete and plastic) where large amounts of water are collected and pumped back to the irrigation ponds on the course. One pit has a 7.5 HP motor-driven pump that is actuated by the



How do you cover a four foot wide sump pit in a playable area? Put a four foot wide lid on it 8" under the soil and grow turf on it. Vent it with a 12" grate.

weight of the water within the pit. If electricity fails, there is a back up generator connected to this pump. In a couple of areas where it was too expensive to run electricity for pumps, Irrigation-Driven Pumps (IDP) were installed to push water to holding ponds. These pumps utilize the energy of the irriga-



All the soil was removed from each trench cut on the property and backfilled with sand.

tion system to pump water. The IDP is placed inside of a sump that has a float in the bottom. When the water level in the sump rises, the float opens a standard 1.5" irrigation valve that has been placed in line between the irriga-

A sliding gate drain (widely used in agricultural fields) regulates the pond depth using a damn principle. (I) View from top (r) gate location relative to pond.





tion system and the IDP. By opening the valve, the water of the irrigation system flows through the pump and creates a vacuum or venturi that sucks the water out of the sump pit. Some homes use this same type of system for sump pumps in their basements as a back up for power loss. They run on the water supply piping in the same fashion. Westmoreland has installed 4 of these pumps on the golf course in areas it was not feasible to install conventional electric pumps.

A key feature of the system is the ability to move water between the ponds to make it available for irrigation or to move water from the ponds into the village's sanitary/storm sewer when needed. Westmoreland employs the use of a sliding drain gate to regulate the pond levels and the amount of water flowing into the village's system during non-heavy rain events either before a storm or the next day after a rain storm. This type of valve controls the discharge rate by creating a dam to regulate the water flow out of the holding structure.



The Leibold construction crew compacting sand in one of the trenches.

Todd explained, "it takes about a day to lower the pond four feet through this structure."

All of the pumps on the golf course discharge into HDPE (high density polyethylene) pipe. The advantages of using HDPE are several: It is butt fused to eliminate potential leak problems at joints. It is highly resistant to corrosion and should last for 100 years. It is also lightweight and flexible.



actuates the pump is triggered by the weight of the water within the sump.

Beside the ponds, there are only few structures above ground that can be seen on the course. Sump pits, where access is not needed are covered by these large aluminum reducers. The one feature that Todd knows the members will see is an increase in turf quality in the coming years. Todd pointed a couple of areas in a fairway that he reseded or sodded each year because of inadequate drainage. Todd has already noticed improvement in the turf in these areas due to their ability to dry out.

Last week my son asked me to quiz him for a science test the following day. He had to know the four components of a healthy soil, 5% organic matter, 45% minerals, 25% water and 25% air - remember that? With the new system installed at Westmoreland that air component can now be part of the equation.



Chris Nelson(L) of Leiblod Irrigation and Todd Fyffe check on of the smaller irrigation driven pumps to make sure it is working as they check the new drainage system late last year.

irrigation system on full. While most superintendents were blowing out their systems, Todd was purposefully flooding a fairway to see how the water moved – from the surface through the soil profile or subsurface drains to the sump pits and into the pond. Each phase of the project was tested to ensure its performance. This enabled Todd, armed with engineering documentation, to show the membership that their investment works. Furthermore Todd has recorded baseline drainage data through soil testing and will continue to document the systems effectiveness into the future. As the

\$2 million project is wrapped up, Todd can enjoy his winter and look forward to a growing turf on soils that drain. The membership of Westmoreland can now look forward to better turf conditions and a significant reduction in the number of "no carts" days following rainfall events.

Thanks to Todd for sharing this project with the membership. As when anyone tells me about a project, my automated response has been to tell them, it sounds like a good article for the membership to me. Todd invited me out to see the project and provided the information for the article. If you have a project or something to share with the membership but don't have the time to get it on paper, let On Course know. We can help. ወ



Once the sod is carefully placed back into the same location, even in the same direction, it is hard to tell all that went on below it...until the next rain event.

When I pulled into the property, Todd was running his

| MAGCS IN MOTION |

Rounds 4 Research and MAGCS

Matt Kregel, The Club at Strawberry Creek

I am pleased to announce that MAGCS will be participating in the Rounds 4 Research program. In 2012 the Environmental Institute for Golf (GCSAA's philanthropic organization) launched the national Rounds 4 Research fund raising campaign having taken it over from the Carolinas GCSA who administered it on a smaller scale for three years.

In 2013, more than 50 GCSAA chapters and organizations participated in the auctions, which raised nearly \$150,000.

Rounds 4 Research is based on the practice of securing donated rounds of golf and putting them up for public auction. The EIFG is working an online auction platform to sell the rounds and administer the various notification and revenue collection activities. At least 80 percent of the proceeds will be distributed to participating chapters or turfgrass organizations for use on research-based programs such as education, scholarships, advocacy and agronomic research.



It will take a committed effort from all of us to make this

program a success. You will be asked to solicit rounds of golf from your facilities (and perhaps others) to be placed for auction. The more rounds we secure the greater the revenue we can generate in support of our members and chapters.

In the near future, we will be providing more information about the program and support documentation that you can share with others at your facility in soliciting rounds and attracting golfers to the auction site. From that perspective, it is important to remember that this program is for the benefit of all aspects of golf. This is not a program that will only benefit golf course superintendents.

Again, I am excited about the opportunity presented to us and the potential to invest in activities that will strengthen the profession and the game. In advance, I appreciate your support and will be communicating more about the program in the near future. Please contact me should you have questions.

Matt Kregel MAGCS Secretary/Treasurer



Servicing the professional golf, lawn care, landscape and sports turf markets

Proudly representing the following Brands...

Armor Tech Products	Holganix Bio
Arysta	Hydro Pak Soil
Barenbrug Seeds	Surfactants
BASE	JRM
Calcium Products	KNOX Fertilizers
EC Grow Fertilizers	Miltona
En P Specialty Liquids	Olsen Brand Fertilizers
	Par Aide
гопаг Рак	SePro
Greenleat	Standard
Greens Groomer	Valent
Greens Groomer	Valerit
(

Aaron Goy Vice President Managing Partner 859.991.0828

Craig Shepherd Regional Agronomist Chicago 563.213.1632 Brett Ziegler Regional Agronomist Chicago/Wisconsin 847.302.9673

Mike Werth Regional Agronomist Wisconsin/Illinois 608.214.7011

Rusty Stachlewitz Regional Agronomist Chicago 630.779.0791

Business & Distribution Center 21969 N. Pepper Rd. Barrington, IL 60010 847.381.9333

Bull Sheet Continued from page 14

On November 26 of last year, TurfNet Blog Aggregator posted one of our member's blogs, and it was noteworthy. First, try to remember what happened earlier that month on the 17th, when our state was hit by an outbreak of deadly tornadoes. Country Club of Peoria superintendent Andy Morris, whose own facility was spared, made the short trip to nearby Washington, IL to visit the Hillcrest Golf Course and offer his help. The photos Andy posted were unbelievable—the destruction to both course and buildings was utterly complete. There were four people in the pro shop when the storm hit, all of whom survived—a miracle considering that the shop was leveled with a car flipped upside down on top of it. Hillcrest is a two-man operation, with owner Brian Brubaker's and superintendent Chuck Bishoff's and their families sole livelihoods hanging in the balance. Andy was asked to serve as their consultant throughout the rebuilding process, a daunting task to say the least. Stories like these remind us of how lucky we are, whether because we were not in harm's way when it happened, or because we have people around us like Andy and the countless others who selflessly pitched in to help others in distress. Let's hope for the best for all the people whose lives were affected on that fateful day.



If you are still on the fence about whether to get down to Orlando for the Conference and Show, there is a pretty snazzy tool you can use called Getting You There—2014 Attendee Justification Resource that can help you out. It can be found at gcsaa.org by clicking on the Golf Industry Show tab. Hurry.

For Sale

2014 Cushman Beverage Cart/Refresher for Sale. \$18,000 or best written offer. Jay Druhan 708-473-8706. Palos Hills Golf Course.



*Not actual beverage cart for sale - stock photo.



Charles Anfield, CGCS, Heritage Bluffs Golf Course

Turf Clinic – Wrap Up (Part 2) - Turf Topics



Dr. Nangle started the turf discussion highlighting the growing conditions of the 2013 season.

The MAGCS Members met at the venerated Medinah Country Club for the 61st Midwest Turf Clinic and Annual Meeting. Curtis Tyrrell, CGCS MG and Staff were the hosts for the day. Turf topics ruled the day.

Dr. Ed Nangle, Director of Turfgrass Programs for the CDGA made his presentation, "2013 A Year in Review." His mission is threefold: to help the CDGA golf course superintendents through diagnostics, research and education. Diagnostic visits to member clubs are helpful to help golf course superintendents identify and control turfgrass disease issues. He conducts field research and product tests with help of the turfgrass program staff to determine current best practices for healthy turf management. Reaching out and helping turf professionals has been a focus of Dr. Nangle since he started this spring with the CDGA. He publishes and distributes approximately 40 weekly scouting reports to more than 400 superintendents, university colleagues and turf industry professionals within the region. His education includes: Post Doctorate Plant Physiology, University of Florida, 2012-2103, Ph.D. Horticulture and Crop Science, The Ohio State University 2012, M.S. Horticulture and Crop Science, The Ohio State University, 2008, B.S. Turfgrass Science and Golf Course Management, Myerscough College, Preston, United Kingdom.

Nangle didn't spend too much time jumping into the year, or spending too much time on covering the spring: The year started out with a cold and wet spring, which was not good for bentgrass. There were small outbreaks of Michrodochium and Waitea patch.

Summer's number one challenge was the management of dollar spot and Nangle chalked up this summer as being the worst in the last 15 years as far as this malady. Rust also became an issue once it warmed and the turf dried out. Rust is not a typical disease that we treat but it did become problematic on newly seeded areas, something the sod industry fights quite a bit. Because most of the summer was dry and we were able to control how much water we put down it wasn't a "big year" for pythium, brown or summer patch. Nor was summer statistically hot or humid at the previous two summers.

Nangle explained, "The climate was comfortable and the rainfall was scattered and mostly bookended,." He credited the phoshite programs as a deterrent to Pythium outbreaks.

Nangle went on to list a few do's and don'ts to turf under stress:

- 1. Do maintain fertility with nitrogen being the most valuable
- 2. Do maintain moisture, stressed turf more susceptible to disease and injury
- 3. Do increase mowing heights when plants are under stress
- 4. Do poke holes for root growth and air exchange
- 5. Don't do the opposite of any of the above

Nangle then went through a few other items that he encountered throughout the summer and through interaction with superintendents.

Weeds: Crabgrass became an issue as early season rains held up applications or were washed away. Knotweed is a growing issue in low-cutting height areas and low fertility turf. Fall herbicide control programs are very important for next season weed control strategies.

Insects: Though dry, insects did not seem to migrate into irrigated areas this summer. Cutworms were a minor problem. Cicada killers were somewhat problematic. They tend to be territorial and can do damage. Control methods have been spotty. Nangle reminded everyone to rotate insect control chemistries to prevent resistance.

Abiotic Factors: There was a lack of intense heat this summer, therefore turfgrass stress was not high. Many courses have had good success with the use of moisture meters. Dr. Nangle